

Zone Revolution Software Change Log

April 2012

April 2012

Software Component	Version	Developer Release	Download File
Zone Revolution Software GUI	2.20	13 February 2012	Zone-REV_install-2.2.0.exe
Zone Revolution Firmware	2.13	13 February 2012	ZONE-Update-2-13.upd

This update provides several improvements addresses several software issues:

- i. The RS485 ICON-CP network is now initialized much quicker, within 1 second of booting.
- ii. Network Subnet Mask and Default Gateway user parameters added to Static IP setup (not implemented with DHCP).

When updating Zone Revolution Firmware from versions earlier than 2.13, this update also implements a hardware watchdog timer and requires a single jumper to be fitted to the DSP board.

NOTE: Once the Revolution firmware has been updated, do not use the older Software GUI, "Emergency Update" or "Revolution Firmware Recovery" tools. These tools are no longer compatible with the new firmware and GUI updater.

23 December 2011

Software Component	Version	Released	Download File
Zone Revolution Software	2.19	23 December 2011	Zone-REV_install-2.1.9.exe
Zone Revolution Firmware	2.12	23 December 2011	ZONE-Update-2-12.upd

This update provides the following improvements:

- i. Solves several data corruption issues that may be experienced following power cycles.
- ii. Master Override Mic/Line 4 signal is now configurable for pre or post zone master routing.

This update also implements a hardware watchdog timer and requires a single jumper to be fitted to the DSP board.

NOTE: Once the Revolution firmware has been updated, do not use the older Software GUI, "Emergency Update" or "Revolution Firmware Recovery" tools. These tools are no longer compatible with the new firmware and GUI updater.